



DEPARTMENT OF NATURAL RESOURCES Division of Oil, Gas & Mining

MICHAEL R. STYLER Executive Director

JOHN R. BAZA Division Director

Inspection Report Minerals Regulatory Program Report Date: September 25, 2006

Supervisor

Tucson, Arizona 85719-6615

Permit number: S/053/028 Mine Name: Picture Spring 1 & 2 Operator Name: Thirstystone Resources, Inc. Date: September 12, 2006 Pete Raymond Time: 4:15 PM 860 East 19th Street

Inspector(s): Doug Jensen Other Participants: None

Weather: Clear, hot Mine Status: Inactive

| Elements of Inspection | Evaluated | Comment | Enforcement |
|---|-----------|---------|-------------|
| 1. Permits, Revisions, Transfer, Bonds | | | |
| 2. Public Safety (shafts, adits, trash, signs, highwalls) | | | |
| 3. Protection of Drainages / Erosion Control | | | |
| 4. Deleterious Material | | | |
| 5. Roads (maintenance, surfacing, dust control, safety) | | | |
| 6. Concurrent Reclamation | | | |
| 7. Backfilling/Grading (trenches, pits, roads, | | | |
| highwalls, shafts, drill holes) | | | |
| 8. Water Impoundments | | | |
| 9. Soils | | | |
| 10. Revegetation | | | |
| 11. Air Quality | | | |
| 12. Other | | | |
| Purpose of Inspection: | | | |
| Check the site while in the area. | | | |

Directions to Site:

See previous inspection report.

Inspection Summary:

This site remains unchanged, there has been no change to this site in several years. There have been a few rocks removed but the removal is probably people no associated with Thirstystone.

Conclusions and Recommendations:

I will continue to monitor this site when I am in the area.

ensen Date: 9/25/06 Inspector's Signature 4

dj:pb

cc:

Pete Raymond

Russ Schreiner, BLM, St George FO UTU 68571

O:\M053-Washington\S0530028-PictureSpring\inspection\09122006insp.doc